

# Wave Distortion Monitor Verification Tester Operation Instructions



Made in the  
United States of America



Figure 1. Desco 98221 Wave Distortion Monitor Verification Tester

## Description

The Desco [98221](#) Wave Distortion Monitor Verification Tester is used to perform periodic test limit verification of [Desco Wave Distortion Monitors](#). Verification may be accomplished without removing the monitor from its workstation. The Wave Distortion Monitor Verification Tester is National Institute of Standards and Technology ([NIST](#)) traceable. Frequency of verification is based on the critical nature of the ESD susceptible items handled. Desco recommends annual calibration of workstation monitors and the Wave Distortion Monitor Verification Tester.

Desco Single-Wire Wave Distortion Continuous Monitors are defined in ESD TR1.0-01-01 as impedance continuous monitors. Most metrology departments or companies specializing in calibration will not have the specialized test equipment needed for the calibration or verification of wave distortion continuous monitors. The Desco 98221 Wave Distortion Monitor Verification Tester meets ANSI/ESD S20.20 and Compliance Verification ESD TR53.

The Desco 98221 Wave Distortion Monitor Verification Tester can be used with the following items:

Item	Description
<a href="#">19239</a>	Mini Monitor
<a href="#">19243</a>	Mini Monitor
<a href="#">19341</a>	Mini Monitor
<a href="#">19342</a>	Mini Monitor
<a href="#">19651</a>	Multi-Mount Monitor
<a href="#">19652</a>	Multi-Mount Monitor
<a href="#">19655</a>	Dual Operator Continuous Monitor
<a href="#">19656</a>	Dual Operator Continuous Monitor
<a href="#">19330</a>	Full-Time Continuous Monitor
<a href="#">19331</a>	Full-Time Continuous Monitor

## Packaging

- 1 Wave Distortion Monitor Verification Tester
- 1 [09700](#) Alligator Clip
- 1 [09782](#) 10mm Stacking Snap
- 1 [09838](#) Ground Plug Adapter
- 1 Banana Plug Wire Adapter, 5"
- 1 Ground Extension Cord, 5'

## Features and Components




Figure 2. Wave Distortion Monitor Verification Tester features and components

- A. Mat Test Lead:** Connect to the monitor's mat terminal to verify its mat test circuit.
- B. Ground Lead:** Connect to equipment ground to provide a ground reference for the Wave Distortion Monitor Verification Tester.
- C. Operator Test Lead:** Insert into the monitor's operator jack to verify its operator test circuit.
- D. Rotary Switch:** Selects the various pass and fail load values needed to verify the monitor's operator and mat test circuits.

## Operation

### 19239/19243 Mini Monitor

#### VERIFYING THE OPERATOR CIRCUIT

1. Connect the Wave Distortion Monitor Verification Tester's green ground lead to equipment ground. This may be done using the included Ground Plug Adapter or alligator clip.




Figure 3. Using the Ground Plug Adapter to ground the Wave Distortion Monitor Verification Tester

2. Insert the verification tester's black operator test lead into the Mini Monitor's operator jack.




Figure 4. Connecting the Wave Distortion Monitor Verification Tester to the Mini Monitor's operator jack

3. Set the rotary switch to OPERATOR FAIL LOW. The monitor's red operator LED should illuminate, and its audible alarm should sound.
4. Set the rotary switch to OPERATOR PASS LOW. The monitor's green operator LED should illuminate.
5. Set the rotary switch to OPERATOR PASS HIGH. The monitor's green operator LED should illuminate.
6. Set the rotary switch to OPERATOR FAIL HIGH. The monitor's red operator LED should illuminate, and its audible alarm should sound.
7. Disconnect the operator test lead from the monitor.

**VERIFYING THE MAT CIRCUIT**

8. If using a discontinued monitor model (see page 7), insert a wrist cord into the monitor's operator jack and attach it to its park snap. This will enable the audible alarm for the mat circuit.
9. Connect the included stacking snap to the verification tester's white mat test lead.
10. Disconnect the monitor from its worksurface mat and turn it over to expose its 10mm snaps.
11. Connect the verification tester's white mat test lead to the monitor's 10mm mat snap.




Figure 5. Connecting the Wave Distortion Monitor Verification Tester to the Mini Monitor's 10mm mat snap

12. Set the rotary switch to MAT 500M PASS. The monitor's green mat LED should illuminate.
13. Set the rotary switch to MAT 500M FAIL. The monitor's red mat LED should illuminate, and its audible alarm should sound.

**19341/19342 Mini Monitor**

**VERIFYING THE OPERATOR CIRCUIT**

1. Connect the Wave Distortion Monitor Verification Tester's green ground lead to equipment ground. This may be done using the included Ground Plug Adapter or alligator clip. See Figure 3.
2. Insert the verification tester's black operator test lead into the Mini Monitor's operator jack.




Figure 6. Connecting the Wave Distortion Monitor Verification Tester to the Mini Monitor's operator jack

3. Set the rotary switch to OPERATOR FAIL LOW. The monitor's operator LED should illuminate red, and its audible alarm should sound.
4. Set the rotary switch to OPERATOR PASS LOW. The monitor's operator LED should illuminate green.
5. Set the rotary switch to OPERATOR PASS HIGH. The monitor's operator LED should illuminate green.
6. Set the rotary switch to OPERATOR FAIL HIGH. The monitor's operator LED should illuminate red, and its audible alarm should sound.
7. Disconnect the operator test lead from the monitor.

## VERIFYING THE MAT CIRCUIT

8. Connect the included alligator clip to the verification tester's white mat test lead.
9. Uninstall the two flathead screws at the bottom of the monitor to free it from its worksurface mat.
10. Reinstall one the flathead screws into the worksurface monitor terminal at the bottom of the monitor.
11. Connect the verification tester's white mat test lead to the flathead screw using the alligator clip.




Figure 7. Using the alligator clip to connect the Wave Distortion Monitor Verification Tester to the Mini Monitor's worksurface monitor terminal

12. Set the rotary switch to MAT 10M PASS. The monitor's worksurface LED should illuminate green.
13. Set the rotary switch to MAT 10M FAIL. The monitor's worksurface LED should illuminate red, and its audible alarm should sound.

## Multi-Mount Monitor

### VERIFYING THE OPERATOR CIRCUIT

1. Connect the Wave Distortion Monitor Verification Tester's green ground lead to equipment ground. This may be done using the included Ground Plug Adapter or alligator clip. See Figure 3.
2. Insert the verification tester's black operator test lead into the Multi-Mount Monitor's operator jack.



Figure 6. Connecting the Wave Distortion Monitor Verification Tester to the Multi-Mount Monitor's operator jack

3. Set the rotary switch to OPERATOR FAIL LOW. The monitor's red operator LED should illuminate, and its audible alarm should sound.
4. Set the rotary switch to OPERATOR PASS LOW. The monitor's green operator LED should illuminate.
5. Set the rotary switch to OPERATOR PASS HIGH. The monitor's green operator LED should illuminate.
6. Set the rotary switch to OPERATOR FAIL HIGH. The monitor's red operator LED should illuminate, and its audible alarm should sound.
7. Disconnect the operator test lead from the monitor.



## VERIFYING THE MAT CIRCUIT

8. If using a discontinued monitor model (see page 7), insert a wrist cord into the monitor's operator jack and attach it to its park snap. This will enable the audible alarm for the mat circuit.
9. Connect the included stacking snap to the verification tester's white mat test lead.
10. Disconnect the monitor's white mat monitor cord from its worksurface mat and turn it over to expose its 10mm snap.
11. Connect the verification tester's white mat test lead to the mat monitor cord's 10mm snap.




Figure 7. Connecting the Wave Distortion Monitor Verification Tester to the Multi-Mount Monitor's mat monitor cord

12. Set the rotary switch to MAT 10M PASS. The monitor's green mat LED should illuminate.
13. Set the rotary switch to MAT 10M FAIL. The monitor's red mat LED should illuminate, and its audible alarm should sound.

## Dual Operator Continuous Monitor

### VERIFYING THE OPERATOR CIRCUIT

1. Connect the Wave Distortion Monitor Verification Tester's green ground lead to equipment ground. This may be done using the included Ground Plug Adapter or alligator clip. See Figure 3.
2. Insert the verification tester's black operator test lead into one of the two operator jacks.




Figure 8. Connecting the Wave Distortion Monitor Verification Tester to the Dual Operator Monitor's operator 1 jack

3. Set the rotary switch to OPERATOR FAIL LOW. The monitor's corresponding operator LED should illuminate red, and its audible alarm should sound.
4. Set the rotary switch to OPERATOR PASS LOW. The monitor's corresponding operator LED should illuminate green.
5. Set the rotary switch to OPERATOR PASS HIGH. The monitor's corresponding operator LED should illuminate green.
6. Set the rotary switch to OPERATOR FAIL HIGH. The monitor's corresponding operator LED should illuminate red, and its audible alarm should sound.
7. Disconnect the operator test lead from the monitor, and connect it to the second operator jack. Repeat the test procedure for the second operator circuit.

## VERIFYING THE MAT CIRCUIT

8. Connect the included stacking snap to the verification tester's white mat test lead.
9. Disconnect the satellite remote's black mat monitor cord from its worksurface mat and turn it over to expose its 10mm snap.
10. Connect the verification tester's white mat test lead to the mat monitor cord's 10mm snap.




Figure 9. Connecting the Wave Distortion Monitor Verification Tester to the Dual Operator Continuous Monitor's mat monitor cord

11. Set the rotary switch to MAT 10M PASS. The monitor's mat LED should illuminate green.
12. Set the rotary switch to MAT 10M FAIL. The monitor's mat LED should illuminate red, and its audible alarm should sound.

## Full-Time Continuous Monitor

### VERIFYING THE OPERATOR CIRCUIT

1. Connect the Wave Distortion Monitor Verification Tester's green ground lead to equipment ground. This may be done using the included Ground Plug Adapter or alligator clip. See Figure 3.
2. Insert the verification tester's black operator test lead into the Full-Time Continuous Monitor's operator jack.



Figure 10. Connecting the Wave Distortion Monitor Verification Tester to the Full-Time Continuous Monitor's operator jack

3. Set the rotary switch to OPERATOR FAIL LOW. The monitor's red operator LED should illuminate, and its audible alarm should sound.
4. Set the rotary switch to OPERATOR PASS LOW. The monitor's green operator LED should illuminate.
5. Set the rotary switch to OPERATOR PASS HIGH. The monitor's green operator LED should illuminate.
6. Set the rotary switch to OPERATOR FAIL HIGH. The monitor's red operator LED should illuminate, and its audible alarm should sound.
7. Disconnect the operator test lead from the monitor.

## VERIFYING THE MAT CIRCUIT

8. Connect the included stacking snap to the verification tester's white mat test lead.
9. Disconnect the monitor's white mat monitor cord from its worksurface mat and turn it over to expose its 10mm snap.
10. Connect the verification tester's white mat test lead to the mat monitor cord's 10mm snap.




Figure 11. Connecting the Wave Distortion Monitor Verification Tester to the Full-Time Continuous Monitor's mat monitor cord

11. Set the rotary switch to MAT 10M PASS. The monitor's green mat LED should illuminate.
12. Set the rotary switch to MAT 10M FAIL. The monitor's red mat LED should illuminate, and its audible alarm should sound.

## Calibration

Frequency of recalibration should be based on the critical nature of those ESD sensitive items handled and the risk of failure for the ESD protective equipment and materials. In general, Desco recommends that calibration be performed annually.

Use the information below to verify if the Wave Distortion Monitor Verification Tester operates within its specifications.

### EQUIPMENT NEEDED

- RLC Bridge for testing operator circuit
- Digital Multimeter with 50-100V power supply for testing mat circuit

### SETTINGS

- @ 50 Hz  
Frequency = 1,000 Hz (20 x 50), 20th harmonic
- @ 60 Hz  
Frequency = 1,020 Hz (17 x 60), 17th harmonic
- Set function switch to read "Equivalent Parallel Circuit"

### RECORD THE FOLLOWING DATA

Operator Rotary Switch Setting	Equivalent Parallel Capacitance	Targeted Specification ( $\pm 10\%$ )
Fail Low		138.9 pF
Pass Low		118.6 pF
Pass High		49.0 pF
Fail High		44.7 pF

Operator Rotary Switch Setting	Dissipation Factor	Targeted Specification ( $\pm 10\%$ )
Fail Low		.158
Pass Low		.367
Pass High		.445
Fail High		.192

Mat Rotary Switch Setting	Resistance @ 50V	Targeted Specification ( $\pm 4\%$ )
10M Pass		8 megohms
10M Fail		12 megohms
100M Pass		80 megohms
100M Fail		120 megohms
500M Pass		400 megohms
500M Fail		600 megohms

## Specifications

Operating Temperature	50 to 95°F (10 to 35°C)
Environmental Requirements	Indoor use only at altitudes less than 6500 ft. (2 km) Maximum relative humidity of 80% up to 85°F (30°C) decreasing linearly to 50% @ 85°F (30°C)
Dimensions	3.17" L x 2.25" W x 1.26" H (81 mm x 57 mm x 32 mm)
Weight	0.3 lbs. (0.15 kg)
Country of Origin	United States of America

The Desco [98221](#) Wave Distortion Monitor Verification Tester may also be used with the following discontinued items:

Jewel® Workstation Continuous Mini Monitor	19212, 19213, 19214, 19215, 19216, 19217, 19218
Multi-Mount Continuous Monitor	19220, 19221, 19222, 19223, 19226, 19227, 19228, 19229, 19234, 19236, 98225, 98226, 98227, 98228
Dual Operator Continuous Monitor	19208, 19209, 19230, 19231, 19232, 19233, 19237, 19238, 19246, 19247, 98207, 98208
Full-Time Continuous Monitor	19210, 19211, 19225, 19321, 19322, 19325, 19326, 50543, 50544, 98210, 98211

### Limited Warranty, Warranty Exclusions, Limit of Liability and RMA Request Instructions

See the Desco Warranty - [Desco.com/Limited-Warranty.aspx](https://Desco.com/Limited-Warranty.aspx)