

Application Instructions Statproof® Dissipative Spray Buff



Made in America



Figure 1. Statproof® Dissipative Spray Buff
Item No. 26028, ready-to-use, 1 quart spray bottle

Description

Statproof® Dissipative Spray Buff is a ready-to-use product specifically designed for use with floors treated with Statproof® Dissipative Floor Finish. Statproof® Spray Buff cleans away surface soils and marks, while repairing scratches and ground-in scuffs. Statproof® Spray Buff renews the surface and brings back the gloss to the floor, while reviving the floor's electrical properties. Our Statproof® Spray Buff can also be used to protect expensive conductive floors.

General Guidelines

Regular intervals of spray buffing will help to maintain floors treated with Statproof® Floor Finish. Spray buffing with Statproof® Dissipative Spray Buff will remove marks and light surface soil while reviving the high gloss and electrical properties of the treated surface.

SPRAY BUFF SCHEDULE

Heavy to moderate foot traffic areas should be spray buffed once a week. Light traffic areas should be buffed 2 to 3 times per month or as needed.

Equipment Needed

- Push broom
 - 1000-1500 rpm buffing machine (with a white or beige pad)
 - Statproof® Spray Buff
1. Sweep away all loose dirt and contaminants. Do not apply spray buff on a floor with loose surface dirt. If the floor is soiled first perform a cleaning procedure using our Statproof® Floor Cleaner.
 2. Lightly spray a small area with the Statproof® ready-to-use Dissipative Spray Buff. Treat a small area at a time.
 3. Buff the sprayed area at 1000-1500 rpm until clean and glossy. The area

must be buffed while in a liquid state. Do not allow it to dry prior to buffing.

4. After high speed buffing, dry mop the entire area with an untreated mop.

Physical Properties

Total Solids: 7 - 8%
Coverage: 10,000-15,000 sq. ft./quart of solution
pH Value: 7 - 9
Color: Light Blue
Storage Temperature:
35°F - 95°F (prevent from freezing)
Freeze/Thaw Stability:
Passes three cycles
Drying Time: 30-60 min. @ 55% RH
Surface Resistivity:
10⁶ - 10⁹ Ohms per ESD S7.1

NOTE: Statproof® Spray Buff does not have a set life span. The chemicals are not known to degrade over time when stored at the proper temperature conditions as stated in the Material Safety Data Sheet. We also recommend that the product be stored in its original container and be sealed when not in use.

Limited Warranty

ESD Systems.com expressly warrants that for a period of one (1) year from the date of purchase, our Statproof® Dissipative Spray Buff will be free of defects in material. Within the warranty period, the material will be replaced at ESD Systems.com option, free of charge. Call Customer Service at 508-485-7390 for a Return Material Authorization (RMA) and proper shipping instructions and address. Include a copy of your original packing slip, invoice, or other proof of purchase date. Any material under warranty should be shipped prepaid to the ESD Systems.com factory.

Warranty Exclusions

THE FOREGOING EXPRESS WARRANTY IS MADE IN LIEU OF ALL OTHER PRODUCT WARRANTIES, EXPRESSED AND IMPLIED, INCLUDING MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE WHICH ARE SPECIFICALLY DISCLAIMED. The express warranty will not apply to defects or damage due to accidents, neglect, misuse, alterations, operator error, or failure to properly maintain, clean or repair products.

Limit of Liability

In no event will ESD Systems.com or any seller be responsible or liable for any injury, loss or damage, direct or consequential, arising out of the use of or the inability to use the product. Before using, users shall determine the suitability of the product for their intended use, and users assume all risk and liability whatsoever in connection therewith.


**Material Safety Data Sheet**

May be used to comply with
OSHA's Hazard Communication Standard,
29 CFR 1910.1200. Standard must be
conformed for specific requirements.

NFPA Designation 704

Degree of Hazard:

4 = Extreme
3 = High
2 = Moderate
1 = Slight
0 = Insignificant



IDENTITY (As Used on Label and List)

STATPROOF® SPRAY BUFF

Section I

Manufacturer's Name

ESD Systems.com

Address (Number, Street, City State and Zip Code)

432 NORTHBORO ROAD CENTRAL,

Emergency Telephone Number

Telephone Number for Information

(508) 485-7390

Date Prepared

11-01-2001

Section II - Hazardous Ingredients/Identity Information

Hazardous Components (Specific Chemical Identity, Common Name(s))

OSHA PEL

ACGIH TLV

Other Limits Recommended

% (optional)

Ethanalamine (CAS -141-43-5)

3ppm

3ppm

Section III - Physical/Chemical Characteristics

Bolling Point	212°F	Specific Gravity (H ₂ O = 1)	8.5-9 lb/gal
Vapor Pressure (mm Hg.)	N/A	Melting Point	N/A
Vapor Density (AIR = 1)	N/A	Evaporation Rate (Butyl Acetate = 1)	N/A

Solubility in Water

pH: 8.5 - 9.0

Complete

Translucent to light blue

Section IV - Fire and Explosion Hazard Data

Flash Point (Method Used)	Flammable Limits	LEL	UEL
N/A	N/A	N/A	N/A
Extinguishing Media			
Water			
Special Fire Fighting Procedures	Unusual Fire and Explosion Hazards		
None	None		

Section V - Reactivity Data

Stability	Unstable	Conditions to Avoid
	Stable	X

Incompatibility (Materials to Avoid)

Hazardous Decomposition or byproducts

N/A

Hazardous Polymerization

May occur

Will Not Occur

X

Section VI - Health Hazard Data

Route(s) of Entry:	Inhalation?	Skin?	Skin Contact	Ingestion?
Health Hazards (Acute and Chronic):				

Carcinogenicity:

NTP?

N/A

IARC Monographs?

N/A

OSHA Regulated?

N/A

Signs and Symptoms of Exposure:

Prolonged contact with skin may cause irritation. Direct contact with eyes may cause irritation.

Medical Conditions

Generally Aggravated by Exposure:

None Known

Emergency and First Aid Procedures:

INHALATION: Remove to fresh air. **SKIN CONTACT:** Flush with water. **EYE CONTACT:** Flush with water; call a physician. **INGESTION:** Do not induce vomiting, drink 3 glasses of water, contact physician.

Section VII - Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled

Soak up with sawdust, sand or earth. Shovel or sweep up. Flush spill area with water.

Waste Disposal Method:

In accordance with local, state and federal regulations.

Precautions to be Taken in Handling and Storing:

Keep from freezing. Keep container closed. Keep out of reach of children. Wash hands with soap and water after use.

Other Precautions:

Mop small spills immediately. Wet film may present slip hazard.

Section VII - Control Measures

Respiratory Protection (Specify Type)

None

Ventilation

Local Exhaust

X

Mechanical (General)

Other

Protective Gloves:

Rubber

Eye Protection:

Goggles

Other Protective Clothing or Equipment:

None

WorkHygienic Practices:

Wash hands before eating, smoking or using washroom facilities.

N/A = Not Applicable; N/E = None Established